Alloy: COREWELD 410NiMo | Class: ER410NiMo

Weld Processes: GMAW • GTAW • SAW (Mig, Tig & Submerged Arc)

CERTIFIED TO
AWS A5.9
ASME SFA A5.9

AWS CHEMICAL COMPOSITION REQUIREMENTS | DEPOSITED CHEMICAL COMPOSITION % (TYPICAL)

AWS REQUIREMENT (%)		TYPICAL DEPOSIT (%)	
C	0.06 max	C	0.02
Si	0.50 max	Mo	0.55
Cr	11.0 – 12.5	P	0.012
P	0.03 max	Cr	11.8
Ni	4.0 – 5.0	Mn	0.45
S	0.03 max	S	0.009
Mo	0.4 – 0.7	Ni	4.50
Cu	0.75 max	Si	0.40
Mn	0.60 max		

DEPOSITED ALL WELD METAL PROPERTIES (R.T.)

MECHANICAL PROPERTY	
Yield Strength	92,000 psi
Tensile Strength	118,000 psi
Elongation	20%

Data is typical for ER410NiMo weld metal deposited by MIG using Argon + 2% oxygen and TIG using 100% Argon as the shielding gas. Data on sub-arc is dependent on the type of flux used.

APPLICATION

COREWELD 410NiMo ER410NiMo wire is used primarily to weld cast and wrought material of similar chemical composition. Recommend using preheat and inter-pass temperature of not less than 300°F. Post weld heat treatment should not exceed 1150°F; higher temperature may result in hardening.

RECOMMENDED WELDING PARAMETERS FOR MIG, TIG & SAW WELDING OF ER410NIMO STAINLESS STEEL

PROCESS	WIRE DIAMETER	WIRE DIAMETER (MM)	WIRE FEED	AMPS	VOLTS	SHIELDING GAS	GAS CFH
GMAW — Short Arc Welding (Reversed Polarity)							
	.030 in	0.80	13–26	40–120	16–20	Argon + 2% O_2	25
	.035 in	0.90	13–26	60–140	16–22	Argon + 2% O_2	25
GMAW — Spray Arc Welding (Reversed Polarity)							
	.035 in	0.90	20–39	140–220	24–29	Argon + 2% O_2	38
	.045 in	1.20	16–30	160–260	25–30	Argon + 2% O_2	38
	1/16 in	1.60	10–16	230–350	27–31	Argon + 2% O_2	38
GTAW — Tig Process (DCRP)							
	.035 in	0.90	—	60–90	12–15	Argon 100%	—
	.045 in	1.20	—	80–110	13–16	Argon 100%	—
	1/16 in	1.60	—	90–130	14–16	Argon 100%	—
	3/32 in	2.40	—	120–175	15–20	Argon 100%	—
Submerged Arc Welding (Reverse Polarity Suggested)							
	3/32 in	2.40	—	250–450	28–32	Suitable flux may be used	—
	1/8 in	3.20	—	300–500	29–34	Suitable flux may be used	—
	5/32 in	4.00	—	400–600	30–35	Suitable flux may be used	—
	3/16 in	4.80	—	500–700	30–35	Suitable flux may be used	—

Note: Parameters for TIG welding are dependent upon plate thickness and welding position. Other shielding gases may be used for MIG and TIG welding; gases are chosen taking quality, cost, and operability into consideration.
Note: Both agglomerated and fused fluxes can be used for submerged arc welding. The chemical composition of the flux mainly affects the chemistry of the weld metal and consequently its corrosion resistance and mechanical properties.

METRACORE ALLOYS PVT LTD.
191 Nawsariwala Building, Shop No 7, Ground Floor, 2nd Kumbharwada Main Road, Near Gol Deval Temple, Mumbai – 400004
Email: sales@metracorealloys.com | Contact: +91-9167564557